



SOFTWARE UPDATE RELEASE NOTES

Product: Fusion Marine Entertainment Systems MS-UD755- MS-AV755

Model: MS-UD755- MS-AV755

Version:

| | |
|--------------------------|----------|
| Stereo | 1.16.520 |
| NRX Series Remote | 1.02.71 |
| DAB Module STM32 C6D28C3 | |
| DAB Tuner | 4.05 |

Bug Fixes:

General bug fixes and improvements
IR Remote play button issue resolved
Loading text issue resolved
BT pairing first device issue resolved
Updated DAB version

Installation Instructions:

To check the installed version of software go to the About Screen in the Settings Menu.

Install Process

1. Download the required zip file to your PC/Laptop.
2. Extract the Update folder to a USB flash drive
3. Connect the USB Flash Drive to the products USB Port.
4. Select the Update feature in the settings menu on the product or via the BT app/F-Link supported MFD or NRX series remote.
5. The Update takes about 1 minute and the "Success" prompt will be displayed once the update is complete.

Important Notes

The Accessory software updates (MS-NRX series/ MS-DAB100A) are imbedded in the MS-AV755/MS-UD755 series update, once the update has been installed in the stereo the connected accessory **MUST** be updated from the update menu screen in the settings menu to be compatible with your Fusion Entertainment System. Please follow the installation instruction (above) or with the update download on the product page.