FUSION®

SOFTWARE UPDATE RELEASE NOTES

Product: Fusion Marine Entertainment System MS-BB100
DAB Module MS-DAB100A
NRX series NMEA 2000 Remote Control

Model: MS-BB100
NRX series Remote Control
            MS-DAB100A DAB Module

Version: 1.1

Build: MS-BB100 : 1.1.50
DAB Module STM32: – 1.01
            DAB Tuner   4.05
NRX Series remote: – 1.02.73

Bug Fixes:

General bug fixes and improvements.
New Remote Version
New DAB version
Re enable tuner updates- DAB
Increase DAB tuner update timeout
Resolve issue with DAB update failure

Important Notes:

The Accessory software updates (MS-NRX remote/MS-DAB100A) are embedded in the MS-BB100 series update, once the update has been installed in the stereo the connected accessory **MUST** be updated from the update menu screen in the settings menu to be compatible with your Fusion Entertainment System. Please follow the installation instruction with the update download on the product page.