



SOFTWARE UPDATE RELEASE NOTES

Product: Fusion Marine Entertainment System MS-BB300
DAB Module MS-DAB100A
NRX series NMEA 2000 Remote Control

Model: MS-BB300
MS-NRX series Remote Control
MS-DAB100A DAB Module

Build: MS-BB300: 2.0.3520
DAB Module C6D28C3
NRX series Remote: – 1.02.71

Bug Fixes:

General bug fixes and improvements.
Fixed Memory Leak causing shutdown (DAB)
Updated DAB version
Updated NRX version

Important Notes:

The Accessory software updates (MS-NRX series/MS-DAB100A) are imbedded in the MS-BB300 update, once the update has been installed in the MS-BB300 the connected accessory **MUST** be updated from the update menu screen in the settings menu to be compatible with your Fusion Entertainment System. Please follow the installation instruction with the update download on the product page.